

**UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION**

BEFORE THE SECRETARY

| |
|---|
| In the Matter of Tennessee Valley Authority Bellefonte Nuclear Power Plant Units 1 and 2 Construction Permits CPPR-122 and CPPR-123 |
|---|

Docket Nos. 50-438 and 50-439

January 11, 2010

**JOINT PETITIONERS' SUPPLEMENTAL BASIS FOR PREVIOUSLY
SUBMITTED CONTENTION 6 – TVA HAS NOT AND CANNOT MEET THE
NRC'S QUALITY ASSURANCE AND QUALITY CONTROL REQUIREMENTS**

In accordance with 10 CFR § 2.309(f)(2), the Blue Ridge Environmental Defense League, its chapter Bellefonte Efficiency and Sustainability Team and the Southern Alliance for Clean Energy (“Petitioners”) hereby submit this new and supplemental basis for Contention 6 which was submitted on May 8, 2009. Contention 6 stated: “The re-instatement was improper because TVA has not and cannot meet the NRC’s Quality Assurance and Quality Control requirements.”

I. BACKGROUND

In the filing of May 8th, Petitioners noted that NRC had withdrawn the construction permits (“CPs”) for BLN Units 1 and 2 on September 14, 2006 and that Bellefonte Units 1 and 2 were therefore outside of the agency’s jurisdiction for an extended period. During this time, the plant had been subject to TVA’s “cannibalism” of

vital structures, systems and components. The lapse is acknowledged in a safety evaluation by the Office of Nuclear Reactor Regulation:¹

Upon reinstatement of the CPs, TVA will resume preservation and maintenance activities consistent with the Commission's Policy Statement on Deferred Plants. (emphasis added)

Petitioners contend that the NRC has ignored, or minimized without justification, regulations codified in 10 CFR 50. Petition at 25.

II. DISCUSSION

Nuclear power plant construction permits are subject to federal regulations which require the prompt identification, evaluation and reporting of defects and failures of nuclear reactor structures, systems and components to the Commission by the holder of the construction permit. It is the responsibility of the "director or responsible officer of a firm constructing...any facility...who obtains information reasonably indicating that the facility, activity, or basic component supplied to such facility or activity contains defects, which could create a substantial safety hazard, to immediately notify the Commission of such failure to comply or such defect." 10 CFR § 21.1. Such notification must be timely; i.e., "in all cases within 60 days of discovery." 10 CFR § 50.55(e). If such identification and evaluation cannot be done within the specified time, an "interim report must be submitted in writing within 60 days of discovery of the deviation." Failure to provide such notification carries a penalty: "Any director or responsible officer of an entity...subject to the regulations in this part who knowingly and consciously fails to

¹ Safety Evaluation by the Office of Nuclear Reactor Regulation Relating to the Request for Reinstatement of Construction Permit Nos. CPPR-122 and CPPR-123, Bellefonte Nuclear Plant, Units 1 and 2, Docket Nos. 50-438 and 50-439 (March 9, 2009)

provide the notice required as by §21.21 shall be subject to a civil penalty equal to the amount provided by section 234 of the Atomic Energy Act of 1954, as amended.” 10 CFR § 21.61(a)

On December 10, 2009 the Tennessee Valley Authority provided notification in writing of a “Containment Vertical Tendon Coupling Failure” which TVA had discovered on August 24, 2009, 108 days previously.² According to TVA, the failure of the containment tendon occurred one week earlier, on August 17th. The actual time of the incident was deduced by TVA based on reports from as yet unidentified individuals who heard a “loud noise.” However, this incident is but the latest example of problems at Bellefonte Units 1 and 2. A 1985 Information Notice details failures same structures at Bellefonte:

During 1975 and 1976 a series of eight rock anchor heads, supplied by INRYCO for the containments at Bellefonte Units 1 and 2, failed during construction installation. In the phased construction process these 170-wire assemblies were sealed for long periods in a highly alkaline water environment. These anchor heads were to be coupled to the posttensioned containment vertical tendons to serve as a direct tie between the containment and the rock foundation material. In these instances the anchor head also broke into several pieces. The licensee's investigations completed on these failures cited several possible contributors. These included: (1) high anchor head stress as a result of a 1.4-inch-diameter hole in the head for grout passage, (2) inclusions in the steel found oriented parallel to the final failure plane, (3) bending of shims and anchor plate, and (4) unknown environmental conditions which facilitated stress corrosion cracking. The NRC had an independent study made that concluded possible stress corrosion cracking as the initiator.

The resolution of the problem resulted in the removal of all the anchor heads and replacement with new anchor heads made from a vacuum degassed (cleaner) steel with the center grout hole eliminated and the anchor head coated for

² Letter from Tennessee Valley Authority Vice President Jack A. Bailey to US Nuclear Regulatory Commission, December 10, 2009, ADAMS Accession No. ML093480158

temporary environmental protection. The NRC is aware of no further failures at Bellefonte after this corrective action.³

The construction period, before nuclear reactor operation has begun, is a critical time for quality assurance and quality control, when some structures receive their greatest stress:

The previous history of anchor head failures before the event at Farley Unit 2, in nuclear applications, has been confined to occurrences during the construction phase (during or shortly after posttensioning). It is during this time that the tendon system, including the anchor head, undergoes the maximum loading force.⁴

Neither TVA nor the Commission can be certain of conditions at Bellefonte during the period after September 2006 when preservation and maintenance activities at Bellefonte had ceased. This lapse may have contributed to the August failure because “rust never sleeps”:⁵

[B]ecause the tendons are fabricated from high-strength steels [>1.6 GPa (230 ksi)] in the form of many relatively small-diameter wires or several strands fabricated from small-diameter wires, and the tendons can be subjected to stresses up to 70% of their ultimate tensile strength, they are more susceptible to corrosion than ordinary reinforcing steels and must be protected.⁶

The failure of the nuclear reactor containment tendon mirrors the failure of TVA to adhere to construction permit conditions which require the permit holder to implement quality assurance criteria. 10 CFR § 50.55.

³ Information Notice No. 85-10: Posttensioned Containment Tendon Anchor Head Failure, IN 85-10, February 6, 1985, Page 2

⁴ *Id*

⁵ “Rust Never Sleeps” (1979) Neil Young and Crazy Horse

⁶ *Overview of the Use of Prestressed Concrete in U.S. Nuclear Power Plants*, H. Astar, NRC Office of Regulatory Research and DJ Naus, Oak Ridge National Laboratory, page 3

In its recent decision regarding Bellefonte, the Commission has determined that it has the authority to reinstate the Bellefonte Construction Permits for Units 1 and 2. The decision was not unanimous. In his dissent, Chairman Jaczko said,

Without continuous regulatory authority, and the associated requirements for maintenance activities and record keeping, the staff loses any assurance of the integrity or reliability of existing structures.

And further,

The potential that undocumented work activities, introduction of unapproved chemicals, corrosion and other unknown degradation has occurred since the QA program was halted calls into question the integrity of and reliability of safety related structures, components and systems.

CLI-10-06 at 24.

The improper environment in the nuclear reactor's containment tendon area, the loss of configuration management program and the history of prior failures all point to further problems at Bellefonte if the Commission were to allow the completion of the virtually moth-eaten 35-year old reactors following years of salvage operations and lack of maintenance and oversight.

III. SATISFACTION OF 10 C.F.R. § 2.309(f)(2).

This supplemental filing satisfies the requirements of 10 C.F.R. § 2.309(f)(2) in the following respects:

First, the information on which the supplemental basis is based, *i.e.*, TVA's letter to NRC was not available to Petitioners until December 10th, well after Petitioners submitted the Petition for Intervention.

Second, the information upon which the new contention is based is materially different than information that was previously available.

Third, this filing has been submitted in a timely fashion because neither the NRC's Power Reactor Event Report No. 45559 nor TVA's letter was available to Petitioners until 30 days ago.

IV. CONCLUSION

For the foregoing reasons, TVA's letter of December 10th and the reference documents cited herein (attached) should be made a part of the record in this proceeding and considered in the context of Petitioner's Contention 6, which asserts that TVA has not and cannot meet the NRC's Quality Assurance and Quality Control requirements.

Respectfully submitted,

A handwritten signature in black ink that reads "Louis A. Zeller". The signature is written in a cursive style and is followed by a horizontal line.

Louis A. Zeller
Blue Ridge Environmental Defense League
PO Box 88
Glendale Springs, NC 28629
Phone: (336) 982-2691 Fax: (336) 977-0852
E-mail: BREDL@skybest.com

**UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION**

BEFORE THE SECRETARY

| |
|---|
| In the Matter of Tennessee Valley Authority Bellefonte Nuclear Power Plant Units 1 and 2 Construction Permits CPPR-122 and CPPR-123 |
|---|

Docket Nos. 50-438 and 50-439

January 11, 2010

CERTIFICATE OF SERVICE

I hereby certify that copies of the Joint Petitioners' Supplemental Basis for Previously Submitted Contention 6—TVA Has Not and Cannot Meet the NRC's Quality Assurance and Quality Control Requirements—were served this day on the following persons via Electronic Information Exchange.

Office of the Secretary
ATTN: Docketing and Service
Mail Stop 0-16C1
US Nuclear Regulatory Commission
Washington, DC 20555-0001
(E-mail: hearingdocket@nrc.gov)

Office of Commission Appellate
Adjudication
US Nuclear Regulatory Commission
Washington, DC 20555-0001
(E-mail: ocaamail@nrc.gov)

Patrick A. Moulding, Esq.
Ann P. Hodgdon, Esq.
US Nuclear Regulatory Commission
Mail Stop O-15 D21
Washington, DC 20555-0001
(E-mail: patrick.moulding@nrc.gov,
ann.hodgdon@nrc.gov)

Louise Gorenflo
Bellefonte Efficiency & Sustainability Team
185 Hood Drive
Crossville, TN 28555
(E-mail: lgorenflo@gmail.com)

Steven P. Frantz, Esq.
Stephen J. Burdick, Esq.
Morgani, Lewis & Bockius LLP
1111 Pennsylvania Ave., NW
Washington, DC 20004
(E-mail: sfrantz@morganlewis.com,
sburdick@morganlewis.com)

Edward J. Vigluicci, Esq.
Scott A. Vance, Esq.
Tennessee Valley Authority
400 West Summit Hill Dr., WT 6A-K
Knoxville, TN 37902
(E-mail: ejvigluicci@tva.gov,
savance@tva.gov)

Maxwell C. Smith, Esq.
Counsel for NRC Staff
US Nuclear Regulatory Commission
Office of the General Counsel
Mail Stop: O-15 D21
Washington, DC 20555-0001
(301) 415-1246
maxwell.smith@nrc.gov


Sara Barczak, Representative of SACE
Southern Alliance for Clean Energy
428 Bull Street
Savannah, GA 31401
(912) 201-0354
sara@cleanenergy.org

Signed this day in Glendale Springs, NC

A handwritten signature in black ink that reads "Louis A. Zeller". The signature is written in a cursive style and is followed by a horizontal line.

Louis A. Zeller
Blue Ridge Environmental Defense
League
PO Box 88 Glendale Springs, NC 28629
(336) 982-2691 (336) 977-0852
(E-mail: BREDL@skybest.com)

January 11, 2010



ISSUE 118: TENDON ANCHOR HEAD FAILURE (REV. 1)

DESCRIPTION

Historical Background

On January 27, 1985, a dented and leaking tendon grease cap was found during inspections at Farley Unit 2 prior to the integrated leak rate test of the prestressed concrete containment structure. Subsequent detailed inspection revealed that three lower vertical tendon anchor heads were broken. Several anchor heads were then removed from the vertical tendons and magnetic particle testing revealed cracks in the ligaments between the holes in the back of the anchor heads. Metallurgical analysis of the anchor head material indicated that the failures had been caused by hydrogen stress-cracking (HSC). There was evidence of corrosion caused by hydrogen generation from the anodic reaction of zinc and steel in the presence of water since quantities of water ranging from a few ounces to about 1.5 gallons were found in the grease caps; most of the water was found in the vertical tendon lower anchor grease caps. Concerns for the generic implications of the tendon anchor failure at Farley Unit 2 resulted in the identification of this issue by DL/NRR. ¹³⁵²

A Task Force was assembled by the NRC to evaluate the anchor failures, including their failure mechanism and the safety significance on Farley and other plants with tendons supplied by the same vendor (INRYCO). The Task Force was to propose corrective action, determine the need for long-term generic action, prepare generic correspondence, and study the potential changes in Regulatory Guide 1.35. ⁴⁸¹ At the time the anchor head cracks were found, Regulatory Guide 1.35 was undergoing revision and the supplemental Regulatory Guide 1.35.1 ¹³⁶⁰ was being developed. Work on these guides was suspended until review of the Farley tendon anchor head failure was completed.

By August 1985, the Farley anchor head failure was also studied by: (1) Inland Steel Laboratory/INRYCO, manufacturer of the Farley post-tension system; (2) Battelle Columbus Laboratories, consultant to INRYCO; and (3) BNL. In November 1985, the Task Force completed its review of the studies by these three laboratories and concluded that cracking of the anchor heads occurred in areas of high stress, was hydrogen-induced, and initiated because of the presence of water, zinc, and sulfur.

Although the Farley Unit 2 problem was concluded to be plant-specific because of the moisture-traveling path to the anchor heads, further study of the contributing factors continued. These factors, in conjunction with the incidence of HSC of anchor heads at Bellefonte and of stress

corrosion cracking of anchor bolt material at Midland, prompted the staff to investigate the potential generic implications and an action plan was developed for resolution of the issue.^{1358,1359} This resolution also addressed the concerns of Issue 156.2.3, "Containment Design and Inspection."

Safety Significance

The failed tendon anchor heads were found to be losing the capability of carrying tendon design force. Tests on cracked anchor heads showed them to be capable of taking the original design force. However, the mechanism of crack initiation and propagation is time-dependent and eventually these anchor heads would not be able to carry the loads. Their failure could jeopardize the containment structural integrity.

Possible Solution

A tendon inspection, repair, and surveillance program was initiated for both Farley Units 1 and 2. The licensee evaluated the containments and concluded that the structural integrity had been maintained continuously for both units. Issuance of Regulatory Guides 1.35⁴⁸¹ and 1.35.1¹³⁶⁰ would provide guidance for future plants.

PRIORITY DETERMINATION

A regulatory analysis¹³⁵³ of the proposed revision 3 to Regulatory Guide 1.35 showed that, although the changes in the guide were determined to produce an unquantifiable change in risk, they would lower the possible risk and enhance containment availability. Additional costs might be incurred by the industry (e.g., visual inspection of bottom grease caps of vertical tendons, and requirements for lift-off tests on the second containment where two identical containments exist at a site), but the relaxed requirements in other areas (i.e., tendon sample size and tendon detensioning) could produce a net cost savings, estimated to be small. It was concluded that backfitting of the revised guide would be very difficult for plants licensed before 1974 and would have to be done on a case-by-case basis, e.g., certain plants do not permit random selection of tendons for detensioning to remove a wire sample for material tests (See Section 6.2, NUREG/CR-4712).¹³⁵³ However, the staff believed that backfitting most plants licensed after 1974 was possible. Regulatory Guide 1.35.1¹³⁶⁰ provided essentially new guidance on predicting and evaluating prestressing forces.

Ten licensee/applicants committed to various provisions of Regulatory Guide 1.35, Rev. 3 (NUREG/CR-4712, Table 4).¹³⁵³ Therefore, the staff's recommendation was to apply the provisions of Rev. 3 to Regulatory Guide 1.35 to new licensing applicants only and allow other licensees to use it on a voluntary basis.¹³⁶¹

The proposed Regulatory Guides 1.35, Rev. 3, and 1.35.1¹³⁶⁰ were reviewed by CRGR in December 1989. CRGR concluded that there did not appear to be any substantial safety improvement in backfitting nor did the matter appear to qualify as a compliance or an adequate protection backfit. CRGR recommended in Meeting No. 175 that the proposed guides be issued for forward-fit only. The guides were issued in July 1990 and only affected future plants and those operating plants that voluntarily committed to the provisions of the guides.

CONCLUSION

A number of licensees voluntarily adopted the provisions of Regulatory Guides 1.35,⁴⁸¹ Rev. 3, and 1.35.1¹³⁶⁰; some SEP plants also developed ISI programs. These actions by some operating plants and the application of these guides to future plants addressed the concerns raised by the Farley Unit 2 tendon anchor head failure. The CRGR decision on the issuance of Regulatory Guides 1.35, Rev. 3, and 1.35.1 indicated that there was no need to backfit operating plants. Thus, this issue was RESOLVED and new requirements were issued. In an RES evaluation,¹⁵⁶⁴ it was concluded that consideration of a 20-year license renewal period did not affect the resolution.

[Privacy Policy](#) | [Site Disclaimer](#)

Friday, February 23, 2007

Overview of the Use of Prestressed Concrete in U.S. Nuclear Power Plants

H. Ashar

*Division of Engineering Technology, Office of Regulatory Research, U.S. Nuclear Regulatory Commission,
Washington, D.C. 20555, U.S.A.*

D.J. Naus

Oak Ridge National Laboratory, P.O. Box Y, Bldg. 9204-1, MS 16, Oak Ridge, Tennessee 37830, U.S.A.

Abstract

The containment system of a nuclear power plant provides a key part of the overall plant's engineered-safety features. The structure serves as the final barrier against release of any radioactive fission products to the environment and consideration of public safety is one of the primary criteria in providing such a barrier.

Originally the containment was envisioned as a static pressure envelope fabricated of steel and which would adequately contain the fission products released from the primary system during any credible accident scenario. As the size of the nuclear power plants increased, the costs of fabricating containment structures from stress-relieved steel plate became significant and it became advantageous to fabricate the containments of concrete. In addition to economic advantages, the concrete containments could be fabricated in virtually any size (thickness) and shape, they generally utilize indigenous materials for their construction, and they exhibit a ductile mode of failure (leak before break) which is predictable and observable. The paper outlines the extent of the use of prestressed concrete containments in nuclear power plants. However, the accident at Three Mile Island has changed the design parameters associated with the containment. In addition to containing the radioactivity during a postulated maximum LOCA, future containment designs should also provide for pressures generated during degraded core accidents. The change might give a slight edge to the application of prestressing in containment design.

The evolution of large size prestressing systems in the United States and abroad has been the result of the need to resist high pressures with the minimum number of tendons. Furthermore, corrosion inhibiting materials evolved simultaneously with the use of large size prestressing tendons. Cement grout and organic-petrolatum-based compounds needed to be specially formulated to assure thorough penetration through the tendon elements. Early in the development of prestressed concrete containments extensive dialogue occurred between the Nuclear Regulatory Commission (known then as the Atomic Energy Commission) and the industry relative to the use of portland cement grout as a corrosion inhibitor. Concern by the regulators relative to the inability to inspect the prestressing tendons to insure their structural integrity resulted in the issuance of two regulatory guides (RGs) by the NRC: (1) "Qualifications for Cement Grouting for Prestressing Tendons in Containment Structures (RG 1.107)" and (2) "Inservice Inspection of Prestressed Concrete Containment Structures with Grouted Tendons (RG 1.90)." According to some observers this action eventually eliminated any incentives for the use of grouted tendons in prestressed concrete containments.

In the United States it is required that the condition and functional capability of the ungrouted post-tensioning systems of prestressed concrete nuclear power plant containments be periodically assessed. This is accomplished, in part, systematically through an inservice tendon inspection program which must be developed and implemented for each containment. An overview of the essential elements of the inservice inspection requirements is presented and the effectiveness of these requirements is demonstrated through presentation of some of the potential problem areas which have been identified through the periodic assessments of the structural integrity of containments. Also, a summary of major problems which have been encountered with prestressed concrete construction at nuclear power plant containments in the United States is presented; that is, dome delamination, cracking of anchorheads, settlement of bearing plates, etc. The paper will conclude with an assessment of the overall effectiveness of the prestressed concrete containments.

1. Introduction

The principal use of prestressed concrete in the U.S. Nuclear Power Plants is in the construction of their containment structures. The containment structure (or containment) is a vital engineering safety feature of a nuclear power plant. It encloses the entire reactor and reactor coolant system, and serves as the final barrier against release of radioactive fission products to the environment under postulated design basis accident (DBA) conditions. To perform this function it is designed to withstand loadings associated with loss-of-coolant accident (LOCA) resulting from a double-ended rupture of the largest size pipe in the reactor coolant system. The containment is also designed to retain its integrity under low probability ($<10^{-4}$) environmental loadings such as those generated by earthquake, tornado and other site specific environmental events such as floods, seiche, and tsunami. Additionally, it is required to provide biological shielding under both normal and accident conditions, and is required to protect the internal equipment from external missiles, such as tornados or turbine generated missiles and aircraft impact (where postulated).

An additional functional requirement for containments has come into play since the accident at Three Mile Island. This requirement consists of maintaining the integrity of the containment under thermal and pressure loads (symmetrical or nonsymmetrical) ensuing from the detonation of hydrogen generated as a result of the metal-water (steam) reaction under degraded core conditions. Dry containments, such as the one at Three Mile Island, which are designed for high LOCA pressures, are not affected by this additional requirement; however, the pressure suppression type containments (PWR ice-condenser, and some BWR containments), designed for low LOCA pressures, are subjected to a thorough evaluation. This requirement may become one of the controlling criteria in the design of future containments.

The functional requirements for containments are satisfied by various types of composite and hybrid steel-concrete constructions. Originally, the containment was envisioned as a static pressure envelope fabricated of steel with a separate radiation shield. As the size of the nuclear power plants increased, the costs of fabricating high pressure containment structures from stress-relieved steel plate became significant, and engineers started looking for alternatives such as steel-lined reinforced concrete which, in addition to economics, had advantages with respect to: improved construction schedules, earlier construction of interior containment structures and erection of equipment, and they can be designed to carry loads other than pressure and temperature (pipe anchors, equipment supports, etc.). Table I presents a distribution of construction types relative to various containment concepts utilized in the United States.

2. Evolution of Containment Configurations and Prestressing Systems

2.1 Containment Configurations

The first prestressed concrete containments were partially prestressed in the vertical direction only with mechanically spliced reinforcing steel in the hoop direction and in the dome. Fully prestressed concrete containments were first built in the late 1960's being cylindrical in shape with shallow dome and resting on a reinforced concrete slab. The dome is prestressed by three sets of tendons at 60° to each other and which are anchored at the side of the thickened dome-cylinder transition (ring girder). The cylinder walls are prestressed with both vertical and hoop tendons. The vertical tendons are anchored at the top to the ring girder and at the bottom of the foundation mat in specially constructed tendon galleries. Anchorage of the hoop tendons is to buttresses protruding from the cylindrical

wall. Initial containment designs used six buttresses with subsequent designs utilizing either three or four buttresses. Although anchorage of hoop tendons at three buttresses, as compared to six, increased the length of tendons and friction force, the combination of a low coefficient of friction ($\mu < 0.1$) of pre-coated prestressing tendons and the reduced number of buttresses and anchorages produced cost savings. It was for these same reasons that the present-day prestressed concrete containment design evolved; that is, a cylinder with hemispherical dome using inverted-U tendons.

2.2 Prestressing Systems

A posttensioned prestressing system consists of a prestressing tendon in combination with methods of stressing and anchoring the tendon to hardened concrete. Three general categories of prestressing systems exist, depending on the type of tendon utilized: wire, strand or bar. The wire systems utilize a grouping of parallel wires. Strand systems utilize groupings of factory-twisted wire. Bar systems utilize a grouping of high-tensile-strength steel bars. Anchorage is provided by wedges, button-heads, or nuts.

The primary evolution in prestressing systems over the past few years has been with respect to system capacity. Prior to the advent of PCCs the prestressing systems were relatively small size; that is, less than 4.45 MN (500 ton) ultimate capacity. The requirement to withstand high forces resulting from a combination of increased volumes and pressures of the dry pressurized-water reactor (PWR) containments necessitated the development of tendon systems with increased capacity [8.0 to 10.7 MN (900 to 1200 ton)]. This development permitted increased spacing of tendons and reduced congestion by almost halving the number of tendons, tendon ducts and anchorages. The large size tendons were developed by using groupings of multi-wire, multi-strand, or bar systems. In the United States, the 8.9 MN (1000 ton) systems approved for use include: (1) BBRV (wire), (2) VSL (strand) and (3) Stressteel S/H (strand).

3. Evolution and Performance of Corrosion Inhibitors for Prestressing Tendons

Prestressed concrete containments essentially are spaced steel structures since their strength is derived from a multitude of steel elements made up of deformed reinforcing bars and prestressing which are present in sufficient quantities to carry imposed tension loads. The prestressing therefore plays a vital role in insuring the structural integrity of the containment throughout its 30- to 40-year design life. However, because the tendons are fabricated from high-strength steels [>1.6 GPa (230 ksi)] in the form of many relatively small-diameter wires or several strands fabricated from small-diameter wires, and the tendons can be subjected to sustained stresses up to 70% of their ultimate tensile strength, they are more susceptible to corrosion than ordinary reinforcing steels and must be protected. Protection of the prestressing steel is generally provided by filling the ducts with portland cement grout or microcrystalline waxes (petrolatums) compounded using organic corrosion inhibitors.

3.1 Grouting

The effectiveness of portland cement grout as a deterrent to corrosion of steel is evidenced by its performance history in prestressed concrete for over 50 years and its use in reinforced concrete construction for over 100 years. Corrosion of steel in correctly formulated concrete (cement) is prevented by the high alkalinity ($\text{pH} > 12.5$) of the $\text{Ca}(\text{OH})_2$, which produces a passivating gamma iron oxide film on the steel surface [1, 2]. When corrosion does occur it is generally the result of a destruction of the passive layer. This

can result from reduction of the alkalinity associated with calcium hydroxide, calcium silicates, and aluminates [3]; from carbonation; or from the presence of high concentrations of chloride, sulfide or nitrate ions. Current grouting materials have evolved over the years to try to ensure that the prestressing materials are completely encapsulated to prevent corrosion; that is, grouts are specially formulated with water reducers and expansive agents to minimize the potentially deleterious effects of water separation and shrinkage.

3.2 Petrolatum-Based Coatings

Although the introduction of petrolatum-based coatings as corrosion protection is much more recent than the use of portland cement grout, the coatings have gained prominence in PCCs in the United States because of their ease of inservice inspections. Additional advantages include: (1) encapsulation provides an approximate 50% reduction in friction factor which permits the use of longer tendons; (2) tendons may be relaxed, retensioned, and replaced as required; and (3) during construction there is the possibility of more efficient scheduling of event sequence because the tendons are protected in the shop.

The petrolatum-based coatings have evolved over the years to better attune the products to the nuclear unbonded tendon containment applications. Initially the product was a casing filler containing polar wetting agents, rust preventative additives, micro-crystalline waxes and proprietary items formulated to be water displacing, self-healing and resistant to electrical conductivity. The next generation of materials were formed by adding a plugging agent to the casing filler to increase the low flow point of the products ($\sim 39^{\circ}\text{C}$ (100°F)) to keep them from seeking loose sheathing joints and flowing into concrete hairline cracks. A subsequent refinement involved incorporation of a light base number (3 mg KOH/gm of product) to provide alkalinity for improved corrosion protection. Finally, the current generation of materials have evolved through a series of modifications to produce products which have been formulated to: increase the viscosity without sacrificing pumpability, raise the congealing point to $57\text{--}63^{\circ}\text{C}$ ($135\text{--}145^{\circ}\text{F}$), increase the resistance to flow from sheathing joints, improve the water resistance, and raise the base number (35 mg KOH/gm product) to provide higher reserve alkalinity [4].

3.3 Overview of the Performance of Prestressing Tendons [4-8]

Prestressed concrete was first used for nuclear pressure vessels in 1960. As of April 1982, 27 prestressed concrete reactor vessels (PCRVs) were either in operation or scheduled for operation in Europe (France, United Kingdom, Spain and Germany) and the United States. In addition, there are 116 containments for pressurized water reactors (PWRs) and 33 containments for heavy-water reactors (HWRs) commissioned or scheduled for commission throughout the world. Of the 116 containments for PWRs, 62 are in the United States. Reviews of the performance of the prestressing tendons in these structures have revealed that corrosion-related incidents are extremely limited. The evolution of corrosion inhibitors and the use of organic-petrolatum-based compounds designed especially for corrosion protection of prestressing materials have virtually eliminated corrosion of prestressing materials. The few incidences of corrosion that were identified, occurred early in the use of prestressed concrete for containment structures. Where these failures involved tendons coated by petroleum-based materials, the failures generally resulted from the use of off-the-shelf corrosion inhibitors that had not been specially formulated for prestressing materials.

4. Problems and Experiences During Construction of PCCs

In general, the development of the various components of prestressing systems has been substantiated by careful study, testing and thorough evaluations by vendors, engineers and regulators. However, there have been a few occasions, either due to breakdown of the quality control, or due to nonscrutinized construction methods, where significant component failures have occurred. The following is a summary of such reported failures.

At Calvert Cliff nuclear plant (Units 1 and 2) some of the bearing plates under anchor heads of vertical tendons became depressed into the concrete [9]. These depressions ranged in size from 0.8 mm (0.03 in.) to 4.8 mm (0.19 in.) and were generally on the inside edges of the plates. Removal of the plates identified the cause to be inadequate concrete compaction under the plates which produced large size voids. The problem was corrected by detensioning the tendons of affected plates, reinstalling the plates, pressure grouting and retensioning.

Failures occurred in the top anchor heads of 170-wire rock anchor tendons at Bellefonte nuclear plant (Units 1 and 2) [10]. Anchorage of the 12.2 m (40 ft) long tendons to the rock was to be performed using a two stage grouting operation. Initially the tendons were to be grouted over about one-half their length to anchor the bottom heads. This was to be followed by addition of sufficient material to grout the tendons over their remaining length except for the final 0.9 to 1.5 m (3 to 5 ft.). Coupling of the containment vertical tendons to the rock anchors was to be by means of threaded coupling devices. However, during installation of the rock anchorages failures of the top anchor heads were observed just prior to the second stage of grouting. One anchor head failure was observed in which failure of 23 of 170 wires in a tendon occurred. (Figures 1-2 note some of the features of the anchor head cracking and fractures.) In-depth metallographical and fractographical examinations in conjunction with the study of the environment indicated that the failures were the result of stress corrosion cracking of highly stressed AISI 4140 anchor heads in an aqueous environment of varying pH levels. In addition it was noted that during the period between the first and second stage grouting the top anchor heads were covered with grease cans filled with lime water having a pH of 11 to 13.

In November 1979 four anchor heads of 179-wire tendons failed between 1 and 64 days after post-tensioning the Unit 1 containment at the Byron nuclear plant [11]. A thorough study of the chemistry, metallurgy and fracture phenomena indicated that the failure was due to tempered-martensite embrittlement. Failures were time delayed and occurred in a decreasing stress field.

Concrete cracking and grease leakage were noted at various locations on the dome surface, predominately in the southern portion as shown in Fig. 3, after tensioning of approximately two-thirds of the dome tendons at Turkey Point Nuclear Power Plant (Unit 3) [12]. After a thorough examination of the concrete materials, construction method and pre-stress tensioning sequence, it was concluded that the dome delaminations were caused by the combined action of inadequate concrete consolidation and weakness at construction joints. Some engineers at NRC, however, believe that the delaminations were caused by exceeding the radial tensile strength of "weak" concrete and that well designed radial reinforcing would help prevent the situation from repeating in the domes of similar containments.

In April 1976, surface cracking and voids in the dome concrete at Unit 3 of Crystal River Nuclear Power Plant were discovered (by accident) after the dome had been constructed

and fully post-tensioned (Fig. 4) [13]. Primary causes of the delaminations were thought to be the use of low quality coarse aggregate materials accompanied by high radial tension forces above the top tendons, and compression-tension interaction. Other potential contributing factors were tendon misalignment and construction methods. Corrective measures included detensioning of some of the tendons, removal of the delaminated cap, installation of top orthogonal and radial reinforcing, and installation of a new cap concrete.

5. Regulatory Requirements and Effectiveness of Inservice Inspections of Prestressing Tendons

5.1 Background

Early in the development of PCCs extensive dialogue occurred between the Nuclear Regulatory Commission (known then as the Atomic Energy Commission) and industry relative to the use of portland cement grout as a corrosion inhibitor. Extensive tests were conducted to ensure adequate penetration of grout through vertical bar, hoop, and vertical strand tendons [14-16]. However, the regulators were concerned about not being able to positively check the integrity of the prestressing system throughout the life of the structure. As a result of discussions and public meetings, two regulatory guides were developed: (1) "Qualifications for Cement Grouting for Prestressing Tendons in Containment Structures (RG 1.107)" and (2) "Inservice Inspection of Prestressed Concrete Containment Structures with Grouted Tendons (RG 1.90)." This action permits the use of grouted tendons in containments without time consuming meetings and discussions. Though the intent was to thoroughly scrutinize grout material and installation, and to periodically check the status of containment, these actions did not encourage the use of grouted tendons in PCCs.

5.2 Regulatory Requirements

In the United States it is required that the condition and functional capability of the unbonded post-tensioning systems of prestressed concrete nuclear power plants be periodically assessed. This is accomplished, in part, systematically through an inservice tendon inspection program which must be developed and implemented for each containment. The basis for conducting the inspections is presented in Regulatory Guide 1.35 "Inservice Inspections of UngROUTED Tendons in Prestressed Concrete Containment Structures (Rev. 2)." The intent of RG 1.35 is to provide utilities with a basis for developing inspection programs and to provide reasonable assurance, when properly implemented, that the structural integrity of the containment was being maintained. The NRC does not require periodic reporting of inspection results except when the technical specification requirements (generally based on RG 1.35) of particular nuclear units are not met, or where there are obvious problems with materials, tendon prestress measurements, and/or an appreciable amount of cracking, grease leakage, etc. Because of the variety of factors such as tendon corrosion, anchorage failure, and material defects which can weaken the containment's structural integrity, the Guide has sought to examine all sources of potential problem areas before they become critical. Basic components covered by the Guide include: sample selection, visual inspection, prestress monitoring tests, tendon material tests and inspections, and inspection of the filler grease.

Tendon sample selection criteria are specified for typical prestressed concrete containments having a shallow dome-shaped roof on cylindrical walls. For the shallow-dome roof containment sample selection includes six dome tendons (two from each 60° group or three from each 90° group), five vertical tendons and ten hoop tendons. For the hemispherical dome-shaped roof containment sample selection criteria include 4% of the U-tendon population

(not less than four) and 4% of the hoop tendon population (not less than nine) with each result rounded to the nearest integer. If no problems are uncovered during the first three surveillances (scheduled 1, 3, and 5 years after the initial structural integrity test) then the criteria for sample selection are relaxed. For the shallow-dome roof containment the criteria become three dome tendons (one from each 60° group or one from each 90° group plus one additional randomly selected dome tendon), three vertical tendons and three hoop tendons. For the hemispherical-dome roof containment the criteria becomes: (1) 2% of the U-tendon population with results rounded off to the nearest integer, but not less than two; and (2) 2% of the hoop tendon population with the result rounded off to the nearest integer but not less than three. In all cases, the tendons are to be selected on a random but representative basis.

Anchorage assembly hardware of all tendons selected for inspection are to be examined visually. The method used for removing grease in order to permit examination of the stressing washers, shims, wedges, and bearing plates should neither increase the effects of corrosion nor damage the steel. During integrated leak rate testing (ILRT), while the containment is at its maximum test pressure, visual examination of the exterior of the concrete surface is performed to detect areas of widespread concrete cracking, spalling or grease leakage.

Stress levels of each of the tendons in the sample selected for inspection are monitored by performing lift-off or other equivalent tests. These tests include the measurement of the tendon-force level with properly calibrated jacks and the simultaneous measurement of elongations. Allowable elongations, jacking loads, tolerances, and the influences of such variables as temperature are to be predetermined. Acceptance criteria for the results state that the prestress force measured for each tendon should be within the limits predicted for the time of the test. No more than one tendon per sample may be considered defective or a reportable condition occurs, and the cause of the defect must be located and corrected. If only one tendon per sample is defective, then two additional tendons (one on each side of the defective) are tested. If either or both of the two additional tendons are defective, a reportable condition occurs and the cause of the defect is located and corrected. Otherwise, the single defective tendon is considered unique and acceptable.

Previously stressed tendon wires or strands from one tendon of each type are to be removed from the containment for examination over their entire length to determine if there is evidence of corrosion or other deleterious effects. At least three samples are to be cut from each wire or strand (each end and mid-length) and tensile tests conducted. Where either stress cycling is suspected or a potentially corrosive environment is thought to exist, tests simulating these conditions are to be conducted. At successive inspections, samples should be selected from different tendons.

A sample of grease from each tendon in the surveillance is to be analyzed and the results compared to the original grease specification. The original grease specification is subject to the ASME Code which has limits on the amounts of impurities that may be present at the time of installation (10 ppm on the quantity of water-soluble chlorides, nitrates, and sulfides, but no limit is specified for water content). Also the presence of voids in the grease is to be noted. The method for checking the presence of grease is to take into account: (1) minimum grease coverage needed for different parts of the anchorage system; (2) influence of temperatures variations; (3) procedure used to uncover possible voids in

grease in trumpet; and (4) requirements imposed by grease specifications, qualification tests and acceptability limits.

5.3 Experiences from Inspections of PCCs [5, 7]

Three instances of tendon force measurements (lift-off tests) have been reported where the force measured was lower than the minimum required prestress level (40 year losses considered). Probably the most frequently found defect is missing buttonheads, but this problem is generally identified during construction or subsequent inservice inspections, and account is also taken in the design for a few non-effective wires in a tendon or group of tendons. Cracking of anchorheads of buttonhead systems made of AISI 4140 steel has also been reported (apparently due to hydrogen stress cracking); but these incidents also have been identified during construction. Two incidences have been reported of grease leakage through cracks to the exterior surface of the containment apparently due to a combination of inadequate duct joints and grease expansion due to thermal effects. There have also been two incidences of grease discoloration due to containments with the probable cause being entry of contaminated rain water into the tendon ducts during construction. Except for one instance in which a significant amount of water was found in several tendon ducts (despite presence of water, corrosion was found to be minor and steps were taken to eliminate recurrence), little water has been found during inspections. Only a few occurrences of wire corrosion have been identified, but these did not result in wire breaks and were so minor that component replacement was not required (it was concluded that the corrosion had occurred prior to filling the ducts with corrosion inhibitor). There have also been a few incidences of incomplete filling of the tendon ducts with corrosion inhibitors, but this has not caused any serious difficulties and has been corrected.

6. Summary

The evolution of containment systems in the United States is presented as well as motivations for changes. Prestressing systems and the mechanisms utilized for providing corrosion protection of these systems are reviewed. A summary of experiences and problems during construction of PCCs is presented. Results obtained indicate that the few construction problems which occurred were identified and remedied prior to a structure being placed in service. A review of regulatory requirements relative to inservice inspections of prestressing tendons is presented. The few incidences of problems or abnormalities that were identified in these inspections were found to be minor in nature and did not threaten the structural integrity of the containments.

In conclusion, the frequency of occurrence of incidences which could lead to a decrease in the functional capability of PCCs is small, especially considering the number of PCCs in service in the United States. Where problems did occur, they generally were the result of construction practices, and were identified and corrected during either the construction phase, the initial structural integrity test, or in subsequent inservice inspections. Thus it can be concluded that the inspections have been effective in achieving their desired objectives of uncovering and correcting potential problem areas.

References

- [1] SHALON, R., RAPHAEL, M., "Influence of Sea Water or Corrosion of Reinforcement," J. Am. Concrete Inst. 30 (12), 1251-68 (June 1959).
- [2] SCOTT, G.N., "Corrosion Protection Properties of Portland Cement Concrete," J. Am. Water Works Assoc. 57, 1038-52 (August 1965).
- [3] VERBECK, G. J., "Mechanisms of Corrosion of Steel in Concrete," Corrosion of Metals in Concrete, Am. Concr. Inst. Special Publication 49, 21-38 (1975).
- [4] NOVAK, C. W., Viscosity Oil Company, Chicago, personal communication to H. Ashar, Nuclear Regulatory Commission (November 11, 1982).
- [5] Technical Report - An International Survey of In-Service Inspection Experience with Prestressed Concrete Pressure Vessels, FIP/3/6, Fédération Internationale de la Précontrainte, Wexham Springs, Slough, United Kingdom (April 1982).
- [6] NAUS, D. J., An evaluation of the Effectiveness of Selected Corrosion Inhibitors for Protecting Prestressing Steels in PCPVs, ORNL/TM/6479, Oak Ridge National Laboratory, Oak Ridge, Tennessee (March 1979).
- [7] DOUGAN, J. R., Evaluation of In-Service Inspections of Greased Prestressing Tendons, ORNL/TM-8275, Oak Ridge National Laboratory, Oak Ridge, Tennessee (September 1982).
- [8] SCHUPACK, M., "A Survey of the Durability Performance of Post-Tensioning Tendons," J. Am. Concr. Inst. 75 (10), 501-510 (October 1978).
- [9] Study Report on Vertical Tendon Bearing Plates, Appendix 50 of Calvert Cliff Nuclear Power Plant Preliminary Safety Analysis Report, NRC-PDR Docket Nos. 50-317 and 50-319 (1972).
- [10] BERRY, W. E., STIEGELMEYER, W. N., BOYD, W. K., Examination of the Cracked Rock Anchor in the TVA Bellefonte Nuclear Power Plant, Battelle Columbus Laboratories, Columbus, Ohio (1976).
- [11] PRESSWALLA, S. E., Report on the Failure Investigation of Post-Tensioning Anchorheads Used in the Byron Nuclear Containment Structure, Inryco, Melrose Park, Illinois, NRC-PDR Docket Nos. 50-454 and 50-455 (1980).
- [12] Containment Dome Report Turkey Point Unit 3, Florida Power and Light Company, NRC-PDR Docket No. 50-250 (1972).
- [13] Reactor Building Dome Delamination Crystal River Unit 3, Florida Power Corporation, NRC-PDR Docket No. 50-302 (1976).
- [14] WERN, A. H., SCHUPACK, M., LARSEN, W., Prestressing System for H. B. Robinson Nuclear Power Plant, Proc. ASCE Power Division (March 1971).
- [15] HAMSTEAD, G. A., et al., Testing of Large Curved Prestressing Tendons, Proc. ASCE Power Division (March 1971).
- [16] SCHUPACK, M., "Grouting Aid for Controlling the Separation of Water for Cement Grout for Grouting Vertical Tendons in Nuclear Concrete Pressure Vessels," Paper 151/75, Experienced in the Design, Construction and Operation of Prestressed Concrete Pressure Vessels and Containments for Nuclear Reactor, Institution of Mechanical Engineers, London (September 1975).

Research sponsored by the Office of Nuclear Regulatory Research, U.S. Nuclear Regulatory Commission under Interagency Agreements 40-551-75 and 40-543-75 with the U.S. Department of Energy under contract W-7405-eng-26 with the Union Carbide Corporation.

By acceptance of this article, the publisher or recipient acknowledges the U.S. Government's right to retain a nonexclusive, royalty-free license in and to any copyright covering the article.



[Home](#) > [Electronic Reading Room](#) > [Document Collections](#) > [General Communications](#) > [Information Notices](#) > 1985 > IN 8

SSINS No.: 6835
IN 85-10

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

February 6, 1985

Information Notice No. 85-10: POSTTENSIONED CONTAINMENT TENDON ANCHOR
HEAD FAILURE

Addressees:

All nuclear power reactor facilities holding an operating license (OL) or a construction permit (CP).

Purpose:

This information notice is provided to alert recipients of current information relating to a potentially significant problem regarding recent failures of 170-wire posttensioned containment tendon anchor heads at Unit 2 of the Farley Nuclear Station. It is expected that recipients will review the information for applicability to their facilities and consider actions, if appropriate, to detect a similar problem at their facilities. However, suggestions contained in this information notice do not constitute NRC requirements; therefore, no specific action or written response is required.

NRC is continuing to obtain and evaluate pertinent information. If specific actions are determined to be required, an additional notification will be made.

Description of Circumstances:

Farley Unit 2

On January 28, 1985, while conducting a preintegrated leak rate test walkdown of the exterior of the containment structure at the Farley Unit 2 facility, an alert utility worker noted grease leakage and a deformed vertical tendon anchor grease cap on the top of the containment ring beam. When the grease cap on the same tendon was inspected in the tendon access gallery, it also revealed a deformed grease cap. Removal of the grease cap showed that the field anchor head had broken into seven pieces. The posttensioning force (approximately 1.5 x 10⁶ pounds) also had been released and numerous broken wires from the 170-wire tendon were found.

On the basis of this finding, the utility removed some additional tendon anchor grease caps. Of the first eight anchor heads uncovered for inspection, one was found to be cracked. Inspection was curtailed until the cracked anchor head can be detensioned. The tendon associated with this anchor head is still transmitting posttensioning force to the containment. The utility determined from their records that the broken anchor head and the cracked anchor head have the same fabrication lot control number.

8502060136

IN 85-10
February 6, 1985
Page 2 of 3

Additionally, the utility has sent some of the pieces of the broken anchor head to two laboratories for a series of tests for failure analysis, including tests on metallurgical, mechanical, chemical and other physical properties. Testing of the corrosion inhibitor grease is under way.

Currently, the utility has personnel from the architect-engineer and the material supplier on-site in the continuing investigation. Neither the NRC nor the licensee has yet fully integrated the information regarding the results of previous tendon surveillance activities at the Farley site into this information notice. Oral information from the licensee indicates the tendons at Farley Unit 2 were posttensioned in early 1977. The unit has been operational since May 1981. The specific tendon whose anchor head failed and the one found with a cracked anchor head were not included in the sample of tendons that were subjected to surveillance activities since the plant began operation. Thus, there is no definitive information currently available on the time of occurrence of the breakup of the one anchor head or the crack formation in the other anchor head.

While no specific conclusions have been reached at this time regarding the cause of the failures, the NRC believes that based on the conversations with the supplier, INRYCO, that all material from the same fabrication lot control number as the failed heads was utilized exclusively at Farley Unit 2.

The previous history of anchor head failures before the event at Farley Unit 2, in nuclear applications, has been confined to occurrences during the construction phase (during or shortly after posttensioning). It is during this time that the tendon system, including the anchor head, undergoes the maximum loading force.

As background information,, previous 170-wire tendon anchor head failures during construction at other facilities are briefly summarized below.

Bellefonte Units 1 and 2

During 1975 and 1976 a series of eight rock anchor heads, supplied by INRYCO for the containments at Bellefonte Units 1 and 2, failed during construction installation. In the phased construction process these 170-wire assemblies were sealed for long periods in a highly alkaline water environment. These anchor heads were to be coupled to the posttensioned containment vertical tendons to serve as a direct tie between the containment and the rock foundation material. In these instances the anchor head also broke into several pieces. The licensee's investigations completed on these failures cited several possible contributors. These included: (1) high anchor head stress as a result of a 1.4-inch-diameter hole in the head for grout passage, (2) inclusions in the steel found oriented parallel to the final failure plane, (3) bending of shims and anchor plate, and (4) unknown environmental conditions which facilitated stress corrosion cracking. The NRC had an independent study made that concluded possible stress corrosion cracking as the initiator.

The resolution of the problem resulted in the removal of all the anchor heads and replacement with new anchor heads made from a vacuum degassed (cleaner)

IN 85-10
February 6, 1985
Page 3 of 3

steel with the center grout hole eliminated and the anchor head coated for temporary environmental protection. The NRC is aware of no further failures at Bellefonte after this corrective action.

Byron Units 1 and 2

In November of 1979 two 170-wire anchor heads on horizontal tendons were reported to have failed during construction of the Byron containments. One failure occurred one day after stressing and seating the tendon and the other occurred 13 days after stressing and seating. By the end of January 1980, two additional anchor heads had been reported as having failed. The supplier of the anchor heads was INRYCO. Investigations were made by INRYCO on the material from seven separate fabrication lots. It was found that the basic steel material used in several of the batches had been manufactured by

a process that utilized vanadium grain refinement causing an incompatibility with the postfabrication heat treatment. This resulted in a different steel chemistry that would have required a higher temperature for proper heat treatment. As a result of this conclusion all anchor heads that had received improper heat treatment for the basic steel chemistry were removed and replaced. The NRC is not aware of any failures at Byron since the corrective action.

Discussion

Because the integrity of the posttensioned concrete containment structure is based on a highly redundant system of numerous tendon elements (several hundred), the failure of one such element in a family of tendons does not jeopardize containment structural capability. It does, however, necessitate a determination that a mechanism or systematic problem has not arisen under service conditions when one such failure in a tendon is revealed. Specific tendon geometry, tendon size, containment design details, and location of individual tendons with lost or lowered strength properties would dictate the critical number of tendons that could be lost before containment integrity is jeopardized.

No specific action or written response is required by this information notice. If you have any questions about this matter, please contact the Regional Administrator of the appropriate regional office or this office.

Edward L. Jordan Director
Division of Emergency Preparedness
and Engineering Response
Office of Inspection and Enforcement

Technical Contact: R. Shewmaker, IE
(301) 492-7432

Attachment: List of Recently Issued IE Information Notices